

ERRATA SHEET

Please note that the following items are incorrectly shown on the schematic and parts list of the Sylvania Service Oscilloscope Type 405:

NOW SHOWN			CHANGE TO		
SYMBOL	VALUE	PART NO.	SYMBOL	VALUE	PART NO.
R118,R151	68K, 2w.	3C-768373-2	R118,R151 R166,R167	82K, 2w. * 120K, 2w. (in parallel)	3C-782373-2 3C-712473-2
R115,R121 R148,R154	10K, 1/2w.	3C-410373-1	R115,R121 R148,R154	6.8K, 1/2w.	3C-468273-1
C116,C137 C139,C140	50x50uf,250v. 20x20uf,450v.	4D-26388	C116,C137 C139,C140	50x50uf,250v. 20x50uf,450v.	4D-26388-2
F101	1 Amp. nor- mal blow	2F-24125-1	F101	1.25 Amp. slo-blo	2F-24125-8
--	--	--	R162,R163, R164,R165	100 ohm, 1/2w. (inserted in CRT deflection plate leads)	3C-410193-1

* In some units, this combination is made up of 100K, 2 watt resistors in parallel (Part No. 3C-710473-2).