

GTE SYLVANIA

FACTORY PREPARED TECHNICAL SERVICE DATA

STEREO HI-FI
SUPPLEMENT 1 TO
BULLETIN: R52-3,-4,-5,-6,-8

File with Bulletin: R52-3,-4,-5,-6,-8.

Entertainment Products Group

SERVICE PUBLICATIONS DEPARTMENT

700 Ellicott Street - Batavia, N.Y.

This supplement lists all code changes to date on the R52-3,-4,-5,-6,-8 chassis.

| <u>CODE</u> | <u>CHASSIS</u> | <u>PANEL CODE</u> | <u>DESCRIPTION OF CHANGE</u> |
|-------------|----------------|-------------------|--|
| 00 | R52-3,-4,-7,-8 | | Initial Production. |
| 01 | R52-3,-4,-7,-8 | | TO INCREASE PHONO BASS RESPONSE AND VOLUME BASS COMPENSATION - C601, C701 removed from circuit. C616, C716 value changed to .022. R606, R706 value changed to 56K. R608, R708 value changed to 5.6K. |

SUPPLEMENT 1 TO BULLETIN: R52-3,-4,-5,-6,-8

SUPPLEMENT 1 TO BULLETIN: R52-3,-4,-5,-6,-8